# 5500 South/5100 West



A UDOT Project

# **CONSTRUCTION UPDATE: April 2020**

Work continues on intersection improvements at 5500 South/5100 West in Hooper. Crews are widening the intersection to add turn lanes on 5500 South.

### WHAT TO EXPECT

- Crews are nearing completion on the south side of the intersection and will begin work on the north side during the week of April 27. To accommodate the work, 5500 South traffic will be directed by flaggers from April 27 - May 1.
- Lanes are narrowed through the intersection and motorists are advised to reduce speeds and watch for lane shifts.
- Residential access will be maintained.

## **CONSTRUCTION SCHEDULE**

- ▶ 5100 West will continue to be closed through early June.
- Project completion is expected by early June.

Please note that construction schedules are subject to change due to weather conditions, emergency situations, or equipment/supply issues. Updates will be posted to UDOT's project webpage: www.udot.utah.gov/go/hooper5500south.



### 5500 South/5100 West // IMPROVED



### **MORE INFORMATION**

For more information, please contact Andy with the project team at (435) 213-2872 or hooper5500south@utah.gov. Construction updates will also be posted to UDOT's project webpage: www.udot.utah.gov/go/hooper5500south.

### **CLOSURES AND DETOUR ROUTE MAP**



